x1

x1

x1

2 USB charger ports(5V3.1A)

1.5 meter cable: USB A TO USB charging

1 USB A TO adapter

1 Drill a hole in the table/furniture/etc.

2 Plug the USB cable to the bottom of the USB charging.

3 Insert the product into the hole and feed the power plug through the plastic fastening nut.



4 Turn the plastic fastening nut as far up the thread as possible.



5 Connect the USB A port to the adapter.

6 Connect the adapter plug into the intended electrical socket.